

Service Bulletin

Types | J 208, J156

Subject | Ignition system IC 100

No. 41 | 04.11.04

GE Jenbacher | Service
Herbert Sonnerer

Tel. +43 | 5244 | 600-2168
Fax +43 | 5244 | 600-42168

herbert.sonnerer@gejenbacher.com
www.gejenbacher.com



GE Jenbacher

Our sub-supplier WOODWARD informed us about a quality defect in a production batch of the ignition system IC 100. On these devices corrosion of a resistor is possible under certain conditions. A temporary failure of the ignition system may result in this case. The batch concerned can be identified through Woodward - part numbers resp. serial numbers; it is a production lot from the year 2003.


Concerned devices:

Woodward part numbers

9210.0002 – all devices

8408-005 - all devices

8408-011- all **Rev. NEW** units with
serial number 1369 8360 and smaller



As a countermeasure WOODWARD has implemented a change in material. Ignition systems with serial numbers outside the range mentioned are no longer affected by the diminished quality and need therefore not to be replaced!

GE Jenbacher together with WOODWARD has decided to prophylactically replace all ignition devices in this part number resp. serial number range with new devices free of charge to prevent a possible defect.

In case that one of the concerned IC 100 ignition systems is mounted on your engine we ask you to contact your GE Jenbacher representative. He will replace the ignition box by a new one free of charge. In order to preclude mixups please quote the respective type of engine management system.

Part number	Ignition system	Engine management
p/n 428395	IC 100	SAM, dia.ne
p/n 428393	IC 100	dia.ne XT

With this procedure we are sure to meet the high expectations on our products' reliability.