

# SERVICE TECHNICIANS INSTRUCTION |

**Verteiler:**

GEJ-Service

Töchter-Service

Servicepartner

ST-014

**No.**

05.08.04

**Date**GE Jenbacher  
H. Sonnerer | Service  
tel 2168 - fax 42168**from**

## Engine room ventilation NEW

In order to optimize the starting performance of GE Jenbacher engines a modification in control of the engine room ventilation (if included in our scope of supply) has been done

With new systems the frequency controled engine room ventilation ist realized like with container modules as a standard. This means that the engine room ventilation runs with minimum speed until the generator switch is closed.

Also the version, room ventilation with multipoint switch, has been modified (Step 2 will be activated not before generator switch ON).

If there are starting problems of single engines in the field (difficulties with synchronising), there will be the possibility to "retrofit" this engine room ventilation NEW. For this a software modification is necessary (activation of version Container in the ventilation control).

Herbert Sonnerer

Service Department

GE Jenbacher