

**The Service Technician Instruction ST-108 has been replaced by the Service Bulletin SB-077.**