

Service Bulletin

Types | General

Subject | New Oil Refill Solenoid Valve

No. 57Rev 1 | 15.11.2006

Rene Steinberger
GE Energy | Jenbacher Service

Tel. +43 | 5244 | 600-2694
Fax +43 | 5244 | 600-42694

rene.steinberger@ge.com
www.gejenbacher.com





Oil Refill Solenoid Valve: New Manual Actuation

The solenoid valve to control the oil refilling is substituted by a different version from an alternative supplier. Reason for this is a lower price with similar functionality. This new version is 100% compatible. The old version solenoid valves 104153 and 369079 are substituted by the new version solenoid valve 431032 and bracket 464844.

Please note the difference in operation:




Figure 1: old version solenoid valve 104153




Figure 2: new version solenoid valve 431032