



Hofer Thomas

Verteiler: Jenbacher Service
Subsidiaries Service
Service Partner

GE Jenbacher GmbH & Co OHG
Achenseestr. 1-3
A-6200 Jenbach, Austria

T +435244 600-2720
thomas.hofer@ge.com

Service Technician Instruction ST – 045 28. April 2006

Type 3: Cylinder liner / scraper ring / piston

The current version of the scraper ring (P/N 337449) has the same outer diameter than the former version (P/N 315951). The inner diameter of the current version is 0,3 mm bigger and the height is 0,2 mm less than the former version. In case of wrong usage piston damage is expected.

The following combinations are permissible. (Check parts identification)

scraper ring	Cylinder line	Piston with piston junk 18 mm – heart shaped bowl-in piston with an emission optimized combustion chamber
P/N 337459	P/N 337332	P/N 375589
P/N 337459	P/N 337332	P/N 375591
P/N 337459	P/N 337332	P/N 375593
P/N 337459	P/N 337332	P/N 394528

scraper ring	Cylinder line	Piston with piston junk 18 mm without an emission optimized combustion chamber
P/N 315951	P/N 315950	P/N 315917
P/N 315951	P/N 315950	P/N 315918
P/N 315951	P/N 315950	P/N 315919
P/N 315951	P/N 315950	P/N 315920

scraper ring	Cylinder line	Piston with piston junk 15 mm without an emission optimized combustion chamber
P/N 247703	P/N 247651	P/N 248934
P/N 247703	P/N 247651	P/N 281139
P/N 247703	P/N 247651	P/N 281142
P/N 247703	P/N 247651	P/N 281144
P/N 247703	P/N 247651	P/N 281147
P/N 247703	P/N 247651	P/N 288509