

Thomas Hofer

Verteiler: Jenbacher Service
Subsidiaries Service
Service Partner

GE Jenbacher GmbH & Co OHG
Achenseestr. 1-3
A-6200 Jenbach, Austria

T +435244 600-2720
thomas.hofer@ge.com

Service Technician Instruction ST – 073 25. April 2007

Release for serial production: new air filter housing J6xxGS-F / J624GS-F

The Blow-by-separator is integrated in the filter bracket. The air filter housing is mainly made of cast and is structurally identical for different cylinder numbers. A separate version of the air filter bracket is necessary for J624GS-F.

Maintenance intervals are not changed compared to the former version. (Air filter exchange when the differential pressure exceeds 10mbar or at latest after 2000 operating hours, blow-by separator exchange after 4000 operating hours)

Parts list 415452 air filter chamber J624GS-F

- ➔ Spare part 416037 air filter
- ➔ Spare part 422884 oil separator

Parts list 497285 air filter chamber J6xxGS-F

- ➔ Spare part 416037 air filter
- ➔ Spare part 422884 oil separator

