



GE Energy

Hofer Thomas

Verteiler: Jenbacher Service
Töchter Service

GE Jenbacher GmbH & Co OHG
Achenseestr. 1-3
A-6200 Jenbach, Austria

T +435244 600-2720
thomas.hofer@ge.com


Service Technican Instruction ST – 040 22. Februar 2006


Additional cooling fan for interface panels with air conditioning.

Additional cooling fan is already standard for new installations. Retrofit in case of temperature problems possible.

Aim: to avoid selective over temperature by air circulation.

P/N 434973





cooling system Fan internal